


Okeanos Explorer ROV Dive Summary



Dive Number	4		
Equipment Deployed			
ROV	Deep Discoverer (D2)		
Camera Platform	Seirios		
ROV Measurements	⊠ CTD	⊠ Depth	
	Scanning Sonar	USBL Position	Heading
	☑ Pitch	⊠ Roll	HD Camera 1
	HD Camera 2	⊠ Low Res Cam 1	Low Res Cam 2
		⊠ Low Res Cam 4	Low Res Cam 5
Equipment Malfunctions	Before the ROV reached bottom the ship lost power and the dive was aborted.		
ROV Dive Summary (from processed ROV data)	Dive Summary: EX1606_DIVE04 ^^^^^^^^^^^^^^^^^^^^^^^^^^^^^^^^^^^		
Special Notes			
Scientists Involved (please provide name, location, affiliation, email)	none		
Purpose of the Dive	NA		
Description of the Dive	Before the ROV reached bottom the ship lost power and the dive was aborted.		

Please direct inquiries to:



NOAA Office of Ocean Exploration & Research 1315 East-West Highway (SSMC3 10th Floor) Silver Spring, MD 20910 (301) 734-1014

