



Supplementary Figure – The unbaited remote underwater video system was used to confirm the occurrence of suspected FSAs observed during hydroacoustic surveys. The frame was constructed from aluminum slip-on fencing materials (Speed-Rail®).